### Ronald Wastewater District - Sanitary Sewer Rehabilitation Project Summary: 2008 CIP (Contract # 09-B)

Neighborhoods: Echo Lake, Richmond Beach, Richmond Highlands

Permits: City of Shoreline Right-of-Way Permit

**Project Areas:** N 185<sup>th</sup> St between Meridian Ave N and 1<sup>st</sup> Ave NE

NW 194<sup>th</sup> PI between Richmond Beach Dr NW and 25<sup>th</sup> Ave NW

NE 167<sup>th</sup> St between Whitman Ave N and Aurora Ave N

**Condition Assessment:** Through the District's ongoing maintenance, TV inspection personnel assess the entire system once every six to eight years, noting the various types and severity of defects in the sewer mainlines. Pipe segments in the 2008 CIP were selected for replacement due to significant roots throughout pipe runs, broken/cracked pipes, bellies, pulled joints, and evidence of infiltration and inflow (I/I).

#### **Cost/Construction:**

Engineer's Estimate: \$515,480 (w/o tax)

Engineer: Scott Christensen, P.E., Kristen Orndorff, CHS Engineers, LLC

Contractor's Bid Price: \$418,105 (w/o tax) Inspector: David Jensen, CHS Engineers

Change Orders: N/A Contractor: Landis & Landis Construction, LLC

Final Construction Cost: \$403,871.76 (w/o tax) Cost per lineal foot main line: \$214.03 per LF

### Replacement/Rehabilitation:

8" Concrete Sanitary Sewer Pipeburst with 8" HDPE: 1,887 LF Cleanouts Installed: 27

Manholes Replaced (48"): 2 Side Sewers Replaced (4" HDPE): 18

Manholes Rehabilitated (Frame, Cover and Neck): 5 Side Sewer Stubs Replaced (6" HDPE): 13

Side Sewers Replaced (6" HDPE): 1

### **Private Replacement/Participation:**

Number of private side sewers in project: 34

Number of property owners that signed up (signed ROE): 21

# Ronald Wastewater District - Sanitary Sewer Rehabilitation Project Summary: 2008 CIP (Contract # 09-B)

					Replacement			
House #	Street	ROE	Old Material	New Material	Side Sewer	Stub (to edge of R/W)	Size	Notes
18505	Meridian Court N	Υ	ABS/Conc	HDPE/PVC	Х		6", 4"	SS replaced
18512	Meridian Court N	Υ	ABS/Conc	HDPE/PVC	Х		6", 4"	SS replaced
18530	Meridian Ave N	Y	ABS/Conc				6", 4"	4" ABS SS connected with 18510 and 18504. Joint SS partly replaced
18510	Meridian Court N		ABS/Conc	HDPE	Х		6", 4"	SS connected with 18530 and 18504
18504	Meridian Court N	Υ	ABS/Conc	HDPE	Х		6", 4"	SS connected with 18530 and 18510
2122	N 185 <sup>th</sup> St	Y	Conc	HDPE	X		4"	Roof/foundation drains connected. SS replaced
2128	N 185 <sup>th</sup> St	Υ	Conc	HDPE	Х		4"	SS replaced
2137	N 185 <sup>th</sup> St	Υ	Conc	HDPE	Х		4"	SS replaced
2134	N 185 <sup>th</sup> St	Υ	PVC	HDPE		х	4"	Stub connected to ex. 4" PVC
2140	N 185 <sup>th</sup> St	Υ	Conc	HDPE	Х		4"	SS replaced
2146	N 185 <sup>th</sup> St	Υ	Conc	HDPE	Х		4"	SS replaced
2152	N 185 <sup>th</sup> St	Υ	Unknown	HDPE	Х		4"	SS replaced
2156	N 185 <sup>th</sup> St	Υ	Unknown	HDPE	Х		4"	SS replaced
2310 2312	N 185 <sup>th</sup> St N 185 <sup>th</sup> St		PVC	HDPE		х	6"	Two (2) 6" PVC SS's connected. Stub replaced with 6" HDPE
2308	N 185 <sup>th</sup> St		PVC	HDPE		х	4"	Stub connected to ex. 4" PVC
2322	N 185 <sup>th</sup> St	Υ	Conc	HDPE	Х		4"	SS replaced
2330	N 185 <sup>th</sup> St	Y	Conc	HDPE	Х		4"	Part replaced inside of ex. 6" Conc
2336	N 185 <sup>th</sup> St		PVC	HDPE			6"	SS connected with 2334. Joint SS replaced on DS property then transition to ex. 6" PVC

# Ronald Wastewater District - Sanitary Sewer Rehabilitation Project Summary: 2008 CIP (Contract # 09-B)

					Replacement			
House #	Street	ROE	Old Material	New Material	Side Sewer	Stub (to edge of R/W)	Size	Notes
2334	N 185 <sup>th</sup> St	Υ	Conc	HDPE	х		6", 4"	SS replaced
2338	N 185 <sup>th</sup> St	Υ	Conc	HDPE	х		4"	SS replaced
2340	N 185 <sup>th</sup> St		Conc	HDPE		х	4"	Stub connected to ex. 4" Conc
18515	N 185 <sup>th</sup> St	Υ	ABS/Conc	HDPE	Х		4"	Part replaced then connected to ex. 4" Conc
18509	N 185 <sup>th</sup> St	Υ	ABS/Conc	HDPE		x, x	4"	Two (2) separate 4" stubs connected to ex. 4" ABS
2520	NW 194 <sup>th</sup> Pl	Υ	ABS	HDPE	Х		4"	Part replaced then connected to ex. 4" ABS
2523	NW 194 <sup>th</sup> Pl		ABS/Conc	HDPE		х	4"	Stub connected to ex. 4" PVC
2526	NW 194 <sup>th</sup> Pl	Υ	Unknown	HDPE	х		4"	SS replaced
2527	NW 194 <sup>th</sup> Pl		Unknown	HDPE		х	4"	Stub connected to ex. 4" PVC
2534	NW 194 <sup>th</sup> Pl		Conc	HDPE		Х	4"	Stub connected to ex. 4" Conc
2533	NW 194 <sup>th</sup> Pl		Unknown	HDPE		х	4"	Stub connected to unknown ex. pipe
2537	NW 194 <sup>th</sup> Pl	Υ	Conc	HDPE	х		4"	SS replaced
16706	Whitman Ave N		ABS/PVC	PVC		Х	4"	Stub connected to ex. 4" ABS
16549	Aurora Ave N		Conc/PVC	PVC		х	6"	Stub connected to ex. 6" PVC
16707	Aurora Ave N		Clay	PVC	Х		4"	SS replaced with 4" PVC